

REPAIR KITS

BRAKE & CAMSHAFT





**SALES
&
CUSTOMER SERVICE**

Tel No : +91-22-2742 7206 / 2742 7207

Fax No : +91-22-2742 2155

Email : sales@mansonsindia.com

PLANT

146 / 7, J.C.I.E., Kamothe, Panvel,

New Bombay - 410209, India

Tel No : +91-22-2742 3014 / 2742 7206

Fax No : +91-22-2742 2155

CORPORATE OFFICE

Bungalow # 8, Garden Homes, St, Vincent

De Paul Society, Khar Danda Rd., Khar (W),

Mumbai - 400052 India.

Tel No : +91-22-2604 3527 / 2605 5902

Fax No : +91-22-2604 3379

WEBSITE

www.mansonsindia.com

WARRANTY COVERAGE

Mansons parts are warranted against defects in material and workmanship, under normal use and service, for the life of the vehicle on which the part was originally installed for the period of 1 year from date of invoice. The warranty is not transferable and proof of purchase is required. Mansons will not be responsible for any labor or freight charges involved in the replacement of any product. Mansons shall be entitled to make its own inspection to determine the validity of the warranty claim. Mansons shall not be liable nor warrant the product in the event of alteration, misuse, overload, negligence or damage caused by others.

BUYERS RESPONSIBILITIES

Buyer is responsible for proper installation, operation, and maintenance as specified in our publication on Mansons International systems and for using the product in recommended application within rated capacities.

CLAIMS

Buyer is required to obtain prior authorization from us or an authorized customer service representative before replacing or returning any part. Buyer may be required to make the product or part claimed to be covered by this warranty available to us and/or returned to us at buyers expense for review & evaluation. Buyer will also need to provide the following information: product model, vehicle mileage, installation date, and product serial number as shown on the serial tag installed on the product, and application and use information.

EXCLUSION & LIMITATIONS

This warranty does not cover any Mansons part that is altered without written permission or fails, malfunctions or is damaged as a result of accident, abuse, or improper installation, maintenance or use.

JURISDICTION

All claims are subject to Mumbai, India Jurisdiction.

THIS WARRANTY IS OUR SOLE WARRANTY IN REGARD TO COVER MANSONS PART. WE MAKE NO OTHER WARRANTIES, EXPRESS OR IMPLIED, OR OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE IN NO EVENT SHALL WE BE RESPONSIBLE FOR SPECIAL, INCIDENTAL, OR CONSEQUENTIAL DAMAGES OF ANY KIND.

MANSONS INTERNATIONAL PRIVATE LIMITED

Head Office : 146/7, J.C.I.E., Kamothe, Panvel,
Navi Mumbai - 410209, India
Tel No : +91-22-2742 3014 / 2742 7206
Fax No : +91-22-2742 2155
Email : sales@mansonsindia.com
Website : www.mansonsindia.com

INDEX

INDEX BY MANSONS REFERENCE

SR. #	MANSONS	OEM REF.	BRAND	PAGE
1	300.075	09.801.02.11.0 S	BPW	9
2	300.085		BPW	9
3	300.086		BPW	9
4	300.088		BPW	9
5	CK1001	03.331.34.02.0 S	BPW	9
		09.801.02.09.0 S	BPW	9
6	BK42380		BPW	10
7	CK1002	03.331.34.05.0 S	BPW	10
		09.801.02.10.0 S	BPW	10
8	CK1023		BPW	10
9	MFQ3337		BPW	10
10	MFQ3338		BPW	10
11	300.037		BPW	11
12	300.076	04.801.00.43.1	BPW	11
13	CK1005	09.801.00.14.0	BPW	11
		09.801.00.14.1	BPW	11
14	CK1019	09.801.00.14.2	BPW	11
		09.801.00.24.2	BPW	11
15	CK1027	03.112.44.30.0 S	BPW	11
16	CK1029	09.801.02.22.0	BPW	12
		09.801.06.09.0	BPW	12
17	CK1031		BPW	12
18	B6242HD		EATON	12
19	110.2001	78500	EATON	12
20	110.2004	127808	EATON	12
21	110.2005		EATON	13
22	110.2009		EATON	13
23	700.539		EATON	13
24	100.4515.31		FRUEHAUF	13
25	700.531		FRUEHAUF	13
26	CK1014		FRUEHAUF	13
27	CK1016		FRUEHAUF	14
28	FSP01		FRUEHAUF	14
29	FSP02		FRUEHAUF	14
30	MFQ3332H		FRUEHAUF	14
31	MFQ3333		FRUEHAUF	14
32	110.2101		FRUEHAUF	14
33	CK1008	AXA-0420-900	FRUEHAUF	15

MANUFACTURER'S NAMES AND PART NUMBERS IN THIS CATALOGUE ARE USED FOR CROSS REFERENCE PURPOSES ONLY
AND DO NOT IMPLY ANYTHING ABOUT THE ORIGIN OR MANUFACTURER OF PRODUCT

SR. #	MANSONS	OEM REF.	BRAND	PAGE
34	CK1009		FRUEHAUF	15
35	CK1030		FRUEHAUF	15
36	CK1005	8.241.000.622	KASBHOER ASCHEN	15
37	CK1019	8.900.020.171	KASBHOER ASCHEN	15
38	CK1004	312.033	LECINENA	16
39	CK1010	312.203	LECINENA	16
40	CK1032		MERCEDES	16
41	MCB04	395.420.0082	MERCEDES	16
		81.50212.0036 S	MAN	16
42	CK1011	307.420.0339	MERCEDES	16
43	100.4515.25		MERITOR (ROR)	17
44	200.502		MERITOR (ROR)	17
45	780.000	AXL-126	MERITOR (ROR)	17
46	780.034		MERITOR (ROR)	17
47	780.035		MERITOR (ROR)	17
48	790.138		MERITOR (ROR)	18
49	790.139		MERITOR (ROR)	18
50	790.148		MERITOR (ROR)	18
51	CK1013	1520520	MERITOR (ROR)	18
52	CK1024	AXL-LM4	MERITOR (ROR)	18
53	FSP01		MERITOR (ROR)	19
54	110.2121		MERITOR (ROR)	19
55	110.2203		MERITOR (ROR)	19
56	110.2207		MERITOR (ROR)	19
57	700.523		MERITOR (ROR)	19
58	780.001		MERITOR (ROR)	19
59	780.012	AXL-140	MERITOR (ROR)	20
60	780.024		MERITOR (ROR)	20
61	790.131		MERITOR (ROR)	20
62	790.132	AXL-122	MERITOR (ROR)	20
63	790.140		MERITOR (ROR)	20
64	790.141		MERITOR (ROR)	21
65	790.143		MERITOR (ROR)	21
66	910.001		MERITOR (ROR)	21
67	CK1006		MONTENGRO	21
68	CK1007		MONTENGRO	21
69	CK1018		SAF	22
70	600.009	3.268.0034.00	SAF	22

MANUFACTURER'S NAMES AND PART NUMBERS IN THIS CATALOGUE ARE USED FOR CROSS REFERENCE PURPOSES ONLY
AND DO NOT IMPLY ANYTHING ABOUT THE ORIGIN OR MANUFACTURER OF PRODUCT



INDEX

SR. #	MANSONS	OEM REF.	BRAND	PAGE
71	600.013		SAF	22
72	600.015		SAF	22
73	600.016		SAF	22
74	600.038		SAF	23
75	600.042	CAS105	SAF	23
76	600.058		SAF	23
77	600.064		SAF	23
78	600.068		SAF	23
79	CK1017		SCANIA	23
80	100.4515.25		SPICER	24
81	110.2305		SPICER	24
82	600.059		TRAILOR	24
83	780.025		TRAILOR	24
84	CK1003		TRAILOR	24
85	CK1018	15205204	TRAILOR	25
86	CK1021		TRAILOR	25
87	FSP01		TRAILOR	25
88	900.505	154259-6	TRAILOR	25
89	CK1026		TRAILOR	25
90	780.037		YORK	26
91	790.133		YORK	26
92	790.137		YORK	26
93	790.146		YORK	26
94	790.147		YORK	26

MANUFACTURER'S NAMES AND PART NUMBERS IN THIS CATALOGUE ARE USED FOR CROSS REFERENCE PURPOSES ONLY
AND DO NOT IMPLY ANYTHING ABOUT THE ORIGIN OR MANUFACTURER OF PRODUCT

INDEX BY ORIGINAL REFERENCE

SR. #	OEM REF.	MANSONS	BRAND	PAGE
1	03.112.44.30.0 S	CK1027	BPW	11
2	03.331.34.02.0 S	CK1001	BPW	9
3	03.331.34.05.0 S	CK1002	BPW	10
4	04.801.00.43.1	300.076	BPW	11
5	09.801.00.14.0	CK1005	BPW	11
6	09.801.00.14.1	CK1005	BPW	11
7	09.801.00.14.2	CK1019	BPW	11
8	09.801.00.24.2	CK1019	BPW	11
9	09.801.02.09.0 S	CK1001	BPW	9
10	09.801.02.10.0 S	CK1002	BPW	10
11	09.801.02.11.0 S	300.075	BPW	9
12	09.801.02.22.0	CK1029	BPW	12
13	09.801.06.09.0	CK1029	BPW	12
14	312.033	CK1004	LECINENA	16
15	312.203	CK1010	LECINENA	16
16	78500	110.2001	EATON	12
17	127808	110.2004	EATON	12
18	1520520	CK1013	MERITOR (ROR)	18
19	15205204	CK1003	TRAILOR	24
20	154259-6	FSP01	TRAILOR	25
21	3.268.0034.00	600.009	SAF	22
22	307.420.0339	CK1011	MERCEDES	16
23	395.420.0082	MCB04	MERCEDES	16
24	8.241.000.622	CK1005	KASSBHOER ASCHEN	15
25	8.900.020.171	CK1019	KASSBHOER ASCHEN	15
26	81.50212.0036 S	MCB04	MAN	16
27	AXA-0420-900	CK1008	FRUEHAUF	15
28	AXL-122	790.132	MERITOR (ROR)	20
29	AXL-126	780.000	MERITOR (ROR)	17
30	AXL-140	780.012	MERITOR (ROR)	20
31	AXL-LM4	CK1024	MERITOR (ROR)	18
32	CAS105	600.042	SAF	23
33		300.085	BPW	9
34		300.086	BPW	9
35		300.088	BPW	9
36		BK42380	BPW	10
37		CK1023	BPW	10
38		MFQ3337	BPW	10

MANUFACTURER'S NAMES AND PART NUMBERS IN THIS CATALOGUE ARE USED FOR CROSS REFERENCE PURPOSES ONLY
AND DO NOT IMPLY ANYTHING ABOUT THE ORIGIN OR MANUFACTURER OF PRODUCT

O E M I N D E X

SR. #	OEM REF.	MANSONS	BRAND	PAGE
39		MFQ3338	BPW	10
40		300.037	BPW	11
41		CK1031	BPW	12
42		B6242HD	EATON	12
43		110.2005	EATON	13
44		110.2009	EATON	13
45		700.539	EATON	13
46		100.4515.31	FRUEHAUF	13
47		700.531	FRUEHAUF	13
48		CK1014	FRUEHAUF	13
49		CK1016	FRUEHAUF	14
50		FSP01	FRUEHAUF	14
51		FSP02	FRUEHAUF	14
52		MFQ3332H	FRUEHAUF	14
53		MFQ3333	FRUEHAUF	14
54		110.2101	FRUEHAUF	14
55		CK1009	FRUEHAUF	15
56		CK1030	FRUEHAUF	15
57		CK1032	MERCEDES	16
58		100.4515.25	MERITOR (ROR)	17
59		200.502	MERITOR (ROR)	17
60		780.034	MERITOR (ROR)	17
61		780.035	MERITOR (ROR)	17
62		790.138	MERITOR (ROR)	18
63		790.139	MERITOR (ROR)	18
64		790.148	MERITOR (ROR)	18
65		FSP01	MERITOR (ROR)	19
66		110.2121	MERITOR (ROR)	19
67		110.2203	MERITOR (ROR)	19
68		110.2207	MERITOR (ROR)	19
69		700.532	MERITOR (ROR)	19
70		780.001	MERITOR (ROR)	19
71		780.024	MERITOR (ROR)	20
72		790.131	MERITOR (ROR)	20
73		790.141	MERITOR (ROR)	20
74		790.140	MERITOR (ROR)	21
75		790.141	MERITOR (ROR)	21
76		790.143	MERITOR (ROR)	21

MANUFACTURER'S NAMES AND PART NUMBERS IN THIS CATALOGUE ARE USED FOR CROSS REFERENCE PURPOSES ONLY
AND DO NOT IMPLY ANYTHING ABOUT THE ORIGIN OR MANUFACTURER OF PRODUCT

SR. #	OEM REF.	MANSONS	BRAND	PAGE
80		CK1006	MONTENGRO	21
81		CK1007	MONTENGRO	21
82		CK1018	SAF	22
83		600.013	SAF	22
84		600.015	SAF	22
85		600.016	SAF	22
86		600.038	SAF	23
87		600.058	SAF	23
88		600.064	SAF	23
89		CK1017	SCANIA	24
90		100.4515.25	SPICER	24
91		110.2305	SPICER	24
92		600.059	TRAILOR	24
93		780.025	TRAILOR	24
94		CK1018	TRAILOR	25
95		CK1021	TRAILOR	25
96		900.505	TRAILOR	25
97		CK1026	TRAILOR	25
98		780.037	YORK	26
99		790.133	YORK	26
100		790.137	YORK	26
101		790.146	YORK	26
102		790.147	YORK	26

MANUFACTURER'S NAMES AND PART NUMBERS IN THIS CATALOGUE ARE USED FOR CROSS REFERENCE PURPOSES ONLY
AND DO NOT IMPLY ANYTHING ABOUT THE ORIGIN OR MANUFACTURER OF PRODUCT

Part No.	OEM No.	Application	Brand
----------	---------	-------------	-------

BRAKE SHOE REPAIR KIT



300.075

09.801.02.11.0 S

Brake shoe repair kit

BPW



300.085

Brake shoe repair kit

BPW



300.086

Brake shoe repair kit
N & R axles

BPW



300.088

Brake shoe repair kit
"H" series axles

BPW



CK1001

03.331.34.02.0 S
09.801.02.09.0 S

Brake shoe repair kit

BPW

Part No.

OEM No.

Application

Brand



BK42380

Brake shoe repair kit
N & R axles

BPW



CK1002

03.331.34.05.0 S
09.801.02.10.0 S

Brake shoe repair kit

BPW



CK1023

Brake shoe repair kit


BPW



MFQ3337

Brake shoe repair kit
H & R axles

BPW



MFQ3338

Brake shoe repair kit
ECO, ECO plus axles

BPW

Part No.

OEM No.

Application

Brand

CAMSHAFT REPAIR KIT



300.037

Camshaft repair kit

BPW



300.076

04.801.00.43.1

Camshaft repair kit

BPW



CK1005

09.801.00.14.0

Camshaft repair kit

BPW

09.801.00.14.1

KASSBOHRER ACHSEN

8.241.000.622



CK1019

09.801.00.14.2

Camshaft repair kit

BPW

09.801.00.24.2

KASSBOHRER ACHSEN

8.900.020.171



CK1027

03.112.44.30.0 S

Camshaft repair kit
H & R axles

BPW

Part No.	OEM No.	Application	Brand
----------	---------	-------------	-------



CK1029	09.801.02.22.0 09.801.06.09.0	Camshaft repair kit N & R axles	BPW
---------------	----------------------------------	------------------------------------	-----

CAMSHAFT REPAIR KIT



CK1031		Camshaft repair kit	BPW
---------------	--	---------------------	-----

BRAKE SHOE REPAIR KIT



B6242HD		Brake shoe repair kit	EATON
----------------	--	-----------------------	-------

CAMSHAFT REPAIR KIT




110.2001	78500	Camshaft repair kit	EATON
-----------------	-------	---------------------	-------





110.2004	127808	Camshaft repair kit	EATON
-----------------	--------	---------------------	-------

	Part No.	OEM No.	Application	Brand
	110.2005		Camshaft repair kit	EATON
	110.2009		Camshaft repair kit	EATON
	700.539		Camshaft repair kit	EATON

BRAKE SHOE REPAIR KIT

	100.4515.31		Brake shoe repair kit	FRUEHAUF
	700.531		Brake shoe repair kit	FRUEHAUF
	CK1014		Brake shoe repair kit (Anchor pin 31.75x63mm)	FRUEHAUF

	Part No.	OEM No.	Application	Brand
	CK1016		Brake shoe repair kit (Anchor pin 31.75x77mm)	FRUEHAUF
	FSP01	154259-6	Brake shoe repair kit (Anchor pin 31.75x55mm)	FRUEHAUF MERITOR (ROR) TRAILOR
	FSP02		Brake shoe repair kit GP axles (Anchor pin 31.75x70mm)	FRUEHAUF
	MFQ3332H		Brake shoe repair kit GP axles (Anchor pin 31.75x70mm)	FRUEHAUF
	MFQ3333		Brake shoe repair kit	FRUEHAUF

CAMSHAFT REPAIR KIT

	110.2101		Camshaft repair kit	FRUEHAUF
---	----------	--	---------------------	----------

	Part No.	OEM No.	Application	Brand
	CK1008	AXA-0420-900	Camshaft repair kit	FRUEHAUF
	CK1009	09.801.00.14.2	Camshaft repair kit INTRAX	FRUEHAUF
	CK1030		Camshaft repair kit	FRUEHAUF
	CK1005	8.241.000.622 09.801.00.14.0 09.801.00.14.1	Camshaft repair kit	KASSBOHRER ACHSEN BPW
	CK1019	8.900.020.171 09.801.00.14.2 09.801.00.24.2	Camshaft repair kit	KASSBOHRER ACHSEN BPW

Part No.

OEM No.

Application

Brand

BRAKE SHOE REPAIR KIT



CK1004

312.033

Brake shoe repair kit

LECINENA



CK1010

312.203

Camshaft repair kit

LECINENA

BRAKE SHOE REPAIR KIT



CK1032

Brake shoe repair kit

MERCEDES




MCB04

395.420.0082
81.50212.0036 S

Brake shoe repair kit

MERCEDES
MAN

CAMSHAFT REPAIR KIT



CK1011


307.420.0339

Camshaft repair kit

MERCEDES

Part No.	OEM No.	Application	Brand
----------	---------	-------------	-------

BRAKE SHOE REPAIR KIT



100.4515.25


Brake shoe repair kit

MERITOR (ROR)
HENDRICKSON
SPICER

200.502

Brake shoe repair kit
Various axles

MERITOR (ROR)



780.000

AXL-126

Brake shoe repair kit
TM axles

MERITOR (ROR)



780.034

Brake shoe repair kit


MERITOR (ROR)



780.035

Brake shoe repair kit

MERITOR (ROR)

	Part No.	OEM No.	Application	Brand
	790.138		Brake shoe repair kit TM axles, quick fit shoes	MERITOR (ROR)
	790.139		Brake shoe repair kit TM axles, quick fit shoes	MERITOR (ROR)
	790.148		Brake shoe repair kit	MERITOR (ROR)
	CK1013	1520520	Brake shoe repair kit	MERITOR (ROR)
	CK1024	AXL-LM4	Brake shoe repair kit LM axles	MERITOR (ROR)

Part No.

OEM No.

Application

Brand



FSP01

154259-6

Brake shoe repair kit
(Anchor pin 31.75x55mm)

MERITOR (ROR)
FRUEHAUF
TRAILOR

CAMSHAFT REPAIR KIT



110.2121

Camshaft repair kit


MERITOR (ROR)



110.2203

Camshaft repair kit

MERITOR (ROR)



110.2207

Camshaft repair kit

MERITOR (ROR)



700.523

Camshaft repair kit
freighter I beam &
mark V axles

MERITOR (ROR)




780.001

Camshaft repair kit
TM, U axles

MERITOR (ROR)

	Part No.	OEM No.	Application	Brand
	780.012	AXL-140	Camshaft repair kit LM, TA axles	MERITOR (ROR)
	780.024		Camshaft repair kit U, TM axles	MERITOR (ROR)
	790.131		Camshaft repair kit TM axles, bronze bush	MERITOR (ROR)
	790.132	AXL-122	Camshaft repair kit TE axles	MERITOR (ROR)
	790.140		Camshaft repair kit TM, TE, axles 2 cams (double of 790.132)	MERITOR (ROR)

	Part No.	OEM No.	Application	Brand
	790.141		Camshaft repair kit TM, axles STD cams	MERITOR (ROR)
	790.143		Camshaft repair kit	MERITOR (ROR)
	910.001		Camshaft repair kit P series drive axles 1.1/2" cams	MERITOR (ROR)

CAMSHAFT REPAIR KIT

	CK1006	8811	Camshaft repair kit	MONTENEGRO
	CK1007		Camshaft repair kit	MONTENEGRO

Part No.	OEM No.	Application	Brand
----------	---------	-------------	-------



CK1018

Brake shoe repair kit

SAF

CAMSHAFT REPAIR KIT



600.009

3.268.0034.00

Camshaft repair kit
SK axles

SAF



600.013

Camshaft repair kit

SAF



600.015

Camshaft repair kit


SAF



600.016

Camshaft repair kit

SAF

	Part No.	OEM No.	Application	Brand
	600.038		Camshaft repair kit SK axles	SAF
	600.042	CAS105	Camshaft repair kit SK axles	SAF
	600.058	3.268.0047.00	Camshaft repair kit SK RS axles	SAF
	600.064	3.268.0048.00	Camshaft repair kit SK RS axles	SAF
	600.068		Camshaft repair kit	SAF


BRAKE SHOE REPAIR KIT



CK1017	154259-6	Brake shoe repair kit	SCANIA
--------	----------	-----------------------	--------

Part No.	OEM No.	Application	Brand
----------	---------	-------------	-------

BRAKE SHOE REPAIR KIT



100.4515.25

Brake shoe repair kit

SPICER
HENDRICKSON
MERITOR (ROR)

CAMSHAFT REPAIR KIT




110.2305

Camshaft repair kit

SPICER

BRAKE SHOE REPAIR KIT



600.059

499176900

Brake shoe repair kit

TRAILOR



780.025

Brake shoe repair kit

TRAILOR



CK1003

15205204

Brake shoe repair kit

TRAILOR

Part No.

OEM No.

Application

Brand

BRAKE SHOE REPAIR KIT



CK1018

Brake shoe repair kit

TRAILOR



CK1021

Brake shoe repair kit

TRAILOR



FSP01

154259-6

Brake shoe repair kit
(Anchor pin 31.75x55mm)TRAILOR
FRUEHAUF
MERITOR (ROR)

CAMSHAFT REPAIR KIT



900.505

Camshaft repair kit

TRAILOR



CK1026

Camshaft shoe repair kit

TRAILOR

Part No.	OEM No.	Application	Brand
----------	---------	-------------	-------

BRAKE SHOE REPAIR KIT



780.037

Brake shoe repair kit

YORK

CAMSHAFT REPAIR KIT



790.133

Camshaft repair kit
160 series axles

YORK



790.137

Camshaft repair kit

YORK



790.146

Camshaft repair kit

YORK



790.147

Camshaft repair kit

YORK

NOTES

[illegible]

